


CASE STUDY



ABBEY UPHOLSTERY FACTORY

Location:
Carrickfergus,
Northern Ireland

Abbey Upholstery Factory was badly affected by a fire in April 2021 which burnt down a large section of the facility. Specwall was used in four phases to help rebuild the internal dividing walls. The majority of these were 6m tall or higher and more than 700m² of Specwall was required.

The factory is made up of more than 7,000m² of floorspace and Specwall was chosen for the refurbishment for three main reasons.

Firstly, to allow the factory to continue operations, walls that fell in the fire needed to be sealed up as soon as possible to keep the elements out. Specwall's fast installation time and the fact it requires no scaffolding made it the perfect choice to complete this job quickly. The modular nature of Specwall also meant that it could be built around existing obstacles with ease.